

Federal Energy Act Report

October 1, 2011 thru September 30, 2012

(Public Record Posted Date: November 1, 2012)

General Information:

Total Number of Active UST Facilities: **7,259**
 Total Number of Active/Inactive USTs: **20,599**

Summary Information For On-Site Inspections:

Number of UST Facilities Inspected: **2,870**
 Percent of UST Facilities in SOC Compliance: **59**

Summary Information For Releases:

Number of Confirmed UST Releases: **367**

Sources and Causes of Environmental Releases from Underground Storage Tanks in Illinois

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	89	24.3	0	0	2	0.5	4	1.1	78	21.3	1	0.3	3	0.8	1	0.3
Piping	19	5.2	0	0	0	0	3	0.8	5	1.4	0	0	2	0.5	9	2.5
Dispenser	2	0.5	0	0	0	0	0	0	0	0	0	0	0	0	2	0.5
Submersible (STP)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Delivery Problem	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Unknown	257	70	0	0	0	0	0	0	0	0	0	0	0	0	257	70
Other	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Totals	367	100	0	0	2	0.5	7	1.9	83	22.7	1	0.3	5	1.3	269	73.3

(source of data: Illinois Environmental Protection Agency)

To view site specific information at the Office of the State Fire Marshal, please visit: <http://webapps.sfm.illinois.gov/ustsearch/>

To view the LUST Incident Tracking Database, please visit: <http://epadata.epa.state.il.us/land/ust/Search.asp>